



# **Avaya Aura™ Communication Manager 5.2 SP #3 Release Notes**

Issue 1  
October 12, 2009

#### Notice

While reasonable efforts were made to ensure that the information in this document was complete and accurate at the time of printing, Avaya Inc. can assume no liability for any errors. Changes and corrections to the information in this document might be incorporated in future releases.

#### Documentation disclaimer

Avaya Inc. is not responsible for any modifications, additions, or deletions to the original published version of this documentation unless such modifications, additions, or deletions were performed by Avaya. Customer and/or End User agree to indemnify and hold harmless Avaya, Avaya's agents, servants and employees against all claims, lawsuits, demands and judgments arising out of, or in connection with, subsequent modifications, additions or deletions to this documentation to the extent made by the Customer or End User.

#### Link disclaimer

Avaya Inc. is not responsible for the contents or reliability of any linked Web sites referenced elsewhere within this documentation, and Avaya does not necessarily endorse the products, services, or information described or offered within them. We cannot guarantee that these links will work all the time and we have no control over the availability of the linked pages.

#### Warranty

Avaya Inc. provides a limited warranty on this product. Refer to your sales agreement to establish the terms of the limited warranty. In addition, Avaya's standard warranty language, as well as information regarding support for this product, while under warranty, is available through the Avaya Support Web site:

<http://www.avaya.com/support>

#### License

USE OR INSTALLATION OF THE PRODUCT INDICATES THE END USER'S ACCEPTANCE OF THE TERMS SET FORTH HEREIN AND THE GENERAL LICENSE TERMS AVAILABLE ON THE AVAYA WEB SITE <http://support.avaya.com/LicenseInfo/> ("GENERAL LICENSE TERMS"). IF YOU DO NOT WISH TO BE BOUND BY THESE TERMS, YOU MUST RETURN THE PRODUCT(S) TO THE POINT OF PURCHASE WITHIN TEN (10) DAYS OF DELIVERY FOR A REFUND OR CREDIT.

Avaya grants End User a license within the scope of the license types described below. The applicable number of licenses and units of capacity for which the license is granted will be one (1), unless a different number of licenses or units of capacity is specified in the Documentation or other materials available to End User. "Designated Processor" means a single stand-alone computing device. "Server" means a Designated Processor that hosts a software application to be accessed by multiple users. "Software" means the computer programs in object code, originally licensed by Avaya and ultimately utilized by End User, whether as stand-alone Products or pre-installed on Hardware. "Hardware" means the standard hardware Products, originally sold by Avaya and ultimately utilized by End User.

#### License type(s)

Concurrent User License (CU). End User may install and use the Software on multiple Designated Processors or one or more Servers, so long as only the licensed number of Units are accessing and using the Software at any given time. A "Unit" means the unit on which Avaya, at its sole discretion, bases the pricing of its licenses and can be, without limitation, an agent, port or user, an e-mail or voice mail account in the name of a person or corporate function (For example, . . . , webmaster or helpdesk), or a directory entry in the administrative database utilized by the Product that permits one user to interface with the Software. Units may be linked to a specific, identified Server.

CPU License (CP). End User may install and use each copy of the Software on a number of Servers up to the number indicated by Avaya provided that the performance capacity of the Server(s) does not exceed the performance capacity specified for the Software. End User may not re-install or operate the Software on Server(s) with a larger performance capacity without Avaya's prior consent and payment of an upgrade fee.

#### Copyright

Except where expressly stated otherwise, the Product is protected by copyright and other laws respecting proprietary rights. Unauthorized reproduction, transfer, and or use can be a criminal, as well as a civil, offense under the applicable law.

#### Third-party components

Certain software programs or portions thereof included in the Product may contain software distributed under third party agreements ("Third Party Components"), which may contain terms that expand or limit rights to use certain portions of the Product ("Third Party Terms"). Information identifying Third Party Components and the Third Party Terms that apply to them is available on the Avaya Support Web site:

<http://support.avaya.com/ThirdPartyLicense/>

#### Preventing toll fraud

"Toll fraud" is the unauthorized use of your telecommunications system by an unauthorized party (for example, a person who is not a corporate employee, agent, subcontractor, or is not working on your company's behalf). Be aware that there can be a risk of toll fraud associated with your system and that, if toll fraud occurs, it can result in substantial additional charges for your telecommunications services.

#### Avaya fraud intervention

If you suspect that you are being victimized by toll fraud and you need technical assistance or support, call Technical Service Center Toll Fraud Intervention Hotline at +1-800-643-2353 for the United States and Canada. For additional support telephone numbers, see the Avaya Support Web site:

<http://www.avaya.com/support>

#### Providing Telecommunications Security

Telecommunications security (of voice, data, and/or video communications) is the prevention of any type of intrusion to (that is, either unauthorized or malicious access to or use of) your company's telecommunications equipment by some party.

Your company's "telecommunications equipment" includes both this Avaya product and any other voice/data/video equipment that can be accessed by this Avaya product (that is, "networked equipment").

An "outside party" is anyone who is not a corporate employee, agent, subcontractor, or is not working on your company's behalf. Whereas, a "malicious party" is anyone (including someone who might be otherwise authorized) who accesses your telecommunications equipment with either malicious or mischievous intent.

Such intrusions might be either to/through synchronous (time-multiplexed and/or circuit-based), or asynchronous (character-, message-, or packet-based) equipment, or interfaces for reasons of:

- Utilization (of capabilities special to the accessed equipment)
- Theft (such as, of intellectual property, financial assets, or toll facility access)
- Eavesdropping (privacy invasions to humans)
- Mischief (troubling, but apparently innocuous, tampering)
- Harm (such as harmful tampering, data loss or alteration, regardless of motive or intent)

Be aware that there might be a risk of unauthorized intrusions associated with your system and/or its networked equipment. Also realize that, if such an intrusion should occur, it might result in a variety of losses to your company (including but not limited to, human/data privacy, intellectual property, material assets, financial resources, labor costs, and/or legal costs).

#### Responsibility for Your Company's Telecommunications Security

The final responsibility for securing both this system and its networked equipment rests with you — Avaya's customer system administrator, your telecommunications peers, and your managers. Base the fulfillment of your responsibility on acquired knowledge and resources from a variety of sources including but not limited to:

- Installation documents
- System administration documents
- Security documents
- Hardware-/software-based security tools
- Shared information between you and your peers
- Telecommunications security experts

To prevent intrusions to your telecommunications equipment, you and your peers must carefully program and configure:

- Your Avaya-provided telecommunications systems and their interfaces
- Your Avaya-provided software applications, as well as their underlying hardware/software platforms and interfaces
- Any other equipment networked to your Avaya products

#### TCP/IP Facilities

Customers might experience differences in product performance, reliability and security depending upon network configurations/design and topologies, even when the product performs as warranted.

#### Standards Compliance

Avaya Inc. is not responsible for any radio or television interference caused by unauthorized modifications of this equipment or the substitution or attachment of connecting cables and equipment other than those specified by Avaya Inc. The correction of interference caused by such unauthorized modifications, substitution or attachment is the responsibility of the user. Pursuant to Part 15 of the Federal Communications Commission (FCC) Rules, the user is cautioned that changes or modifications not expressly approved by Avaya Inc. might void the user's authority to operate this equipment.

## Federal Communications Commission Statement

### Part 15:

Note: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

### Canadian Department of Communications (DOC) Interference Information

This Class A digital apparatus complies with Canadian ICES-003.

Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

This equipment meets the applicable Industry Canada Terminal Equipment Technical Specifications. This is confirmed by the registration number. The abbreviation, IC, before the registration number signifies that registration was performed based on a Declaration of Conformity indicating that Industry Canada technical specifications were met. It does not imply that Industry Canada approved the equipment.

### European Union Declarations of Conformity



Avaya Inc. declares that the equipment specified in this document bearing the "CE" (*Conformité Européenne*) mark conforms to the European Union Radio and Telecommunications Terminal Equipment Directive (1999/5/EC), including the Electromagnetic Compatibility Directive (89/336/EEC) and Low Voltage Directive (73/23/EEC).

Copies of these Declarations of Conformity (DoCs) can be obtained by contacting your local sales representative and are available on the Avaya Support Web site:

<http://www.avaya.com/support>

### Trademarks

Avaya, the Avaya logo, DEFINITY, MultiVantage, and COMPAS are either registered trademarks or trademarks of Avaya Inc. in the United States of America and/or other jurisdictions.

All other trademarks are the property of their respective owners.

### Downloading documents

For the most current versions of documentation, see the Avaya Support Web site:

<http://www.avaya.com/support>

### Avaya support

Avaya provides a telephone number for you to use to report problems or to ask questions about your product. The support telephone number is 1-800-242-2121 in the United States. For additional support telephone numbers, see the Avaya Support Web site:

<http://www.avaya.com/support>

## Contents

|   |           |
|---|-----------|
| <b>Changes delivered to Communication Manager 5.2 SP #3 . . . . .</b> | <b>3</b>  |
| <b>Communication Manager 5.2 SP #3 Release Notes . . . . .</b>        | <b>3</b>  |
| <b>Product Support Notices . . . . .</b>                              | <b>3</b>  |
| <b>Communication Manager Messaging . . . . .</b>                      | <b>4</b>  |
| <b>Enhancements . . . . .</b>   | <b>4</b>  |
| <b>Problems fixed in Communication Manager 5.2 SP #0 . . . . .</b>    | <b>5</b>  |
| <b>Problems fixed in Communication Manager 5.2 SP #1 . . . . .</b>    | <b>6</b>  |
| <b>Problems fixed in Communication Manager 5.2 SP #2 . . . . .</b>    | <b>9</b>  |
| <b>Problems fixed in Communication Manager 5.2 SP #2.01 . . . . .</b> | <b>19</b> |
| <b>Problems fixed in Communication Manager 5.2 SP #3 . . . . .</b>    | <b>20</b> |
| <b>Known problems. . . . .</b>  | <b>32</b> |
| <b>Technical Support . . . . .</b>                                    | <b>39</b> |
| <b>Appendix A: Acronyms . . . . .</b>                                 | <b>41</b> |

## Contents

# Changes delivered to Communication Manager 5.2 SP #3

---

## Communication Manager 5.2 SP #3 Release Notes

The **Communication Manager** service packs are cumulative and changes in **Communication Manager 5.2 SP#0**, **SP#1**, **SP#2**, and **SP#2.01** are included in **Communication Manager 5.2 SP#3**. The changes delivered to **Communication Manager 5.2 SP #3** are grouped as follows:

- [Table 1: Enhancements delivered to Communication Manager 5.2 SP #2](#) on page 4
- [Table 2: Fixes delivered to Communication Manager 5.2 SP #0](#) on page 5
- [Table 3: Fixes delivered to Communication Manager 5.2 SP #1](#) on page 6
- [Table 4: Fixes delivered to Communication Manager 5.2 SP #2](#) on page 9
- [Table 5: Fixes delivered to Communication Manager 5.2 SP #2.01](#) on page 19
- [Table 6: Fixes delivered to Communication Manager 5.2 SP #3](#) on page 20
- [Table 7: Known problems in Communication Manager 5.2 SP #3](#) on page 32

Refer to the latest **Communication Manager** Software & Firmware Compatibility Matrix at <http://support.avaya.com> for supported upgrade paths between **Communication Manager** releases and service packs. The supported upgrade paths account for both **Communication Manager** internal data translation records as well as 100% inclusion of bugfixes.

---

## Product Support Notices

Some problems are also documented as Product Support Notices (PSN). The PSN number defines the related document and appears in the Problem column in the tables.

To read the PSN description online:

1. Go to the Avaya support site at <http://support.avaya.com>.
2. Under **Product Notices**, click **Product Support Notices**.  
The alphabetical list of documentation is displayed.
3. Click letter **P** in that list. All documents starting with letter **P** are displayed.

4. Click **Product Support Notices (All Avaya Products)**.  
The **Product Support Notices (All Avaya Products)** page is displayed.
5. In the web browser's **Find in Page** function, type the last four digits of the PSN number to search a link to the PSN on the page.
6. Click the PSN title link to open the PSN.

---

## Communication Manager Messaging

For information regarding Communication Manager Messaging Service Packs (RFUs):

1. Go to the Avaya support site at <http://support.avaya.com>.
2. Click **Products**. The **Enter Product Name** box is displayed.
3. Click **A-Z list**. The alphabetical list of documentation is displayed.
4. Click letter **C** in that list. All documents starting with letter **I** are displayed.
5. Click **Communication Manager Messaging**.  
The overview of **Communication Manager Messaging** is displayed.
6. Under **Product Information**, click **Downloads**.
7. Choose the appropriate release from the drop-down list and click the link to the **Communication Manager Messaging - Release x.y.z**.

---

## Enhancements

This release includes the following changes that are new to **Communication Manager**.

**Table 1: Enhancements delivered to Communication Manager 5.2 SP #2**

| Enhancement  | Keywords | Workaround |
|--|----------|------------|
| Previously the "Force Phones and Gateways to Active <b>LSPs</b> " field on the system-parameter ip-options form was not administrable by customer login IDs. | 083408   |            |
| When the duplication link went down, a major alarm was logged immediately without any resolution to retire the alarm.  | 091287   |            |
|  |          |            |

## Problems fixed in Communication Manager 5.2 SP #0

This release includes the following fixes delivered to **Communication Manager**.

**Table 2: Fixes delivered to Communication Manager 5.2 SP #0 1 of 2**

| Problem  | Keywords | Workaround |
|--|----------|------------|
| When a call over trunks was forwarded to the Bridge Appearance ( <b>BA</b> ) of an Administration Without Hardware ( <b>AWOH</b> ) station, it did not term on to the Toshiba <b>SIP</b> Phone having the <b>BA</b> .  | 091238   |            |
| Whenever calls over a trunk were transferred locally to the Bridge Appearance ( <b>BA</b> ) of an Administration Without Hardware ( <b>AWOH</b> ) station, or a local call to <b>BA</b> was transferred over a trunk, the line 1 display on the party having the <b>BA</b> goes blank after transfer is complete. It should have shown the connected party's number instead. | 091258   |            |
| On server type S8730 the command <code>hardware info</code> did not display any information about the hard disk drives.  | 091284   |            |
| In response to a particular error condition for a <b>SIP</b> call, <b>Communication Manager</b> did not clear the failed call correctly, resulting in a memory-access error that could lead to a system restart.   | 091288   |            |
| Under certain conditions, an internal <b>Communication Manager</b> error may result in a system restart.   | 091292   |            |
| Look Ahead Routing not invoked when primary trunk disconnected or on system busy and call is on coverage on that primary trunk.  | 091322   |            |
| After a server interchange on a Processor Ethernet for Duplicated Servers system, <b>Communication Manager</b> could experience an extra system restart.   | 091341   |            |
| Under very high system traffic conditions a system reset (cold-2) could happen.  | 091342   |            |
| With the use of Shared Mapping feature, under certain circumstances when calling from cell phone to any desk set, calling party will not be able to see caller's desk set name and number instead it sees caller's cell phone number.  | 091357   |            |
| On rare occasions when the "Force Phones and Gateways to Active LSPs" field is marked 'y', a change in <b>LSP</b> status can result in a warm start.   | 091359   |            |
| <b>1 of 2</b>  |          |            |

**Table 2: Fixes delivered to Communication Manager 5.2 SP #0 2 of 2**

| Problem  | Keywords | Workaround    |
|--|----------|---------------|
| <b>SIP</b> signaling groups may not have a listen socket established leading to <b>SIP</b> trunking failures.  | 091362   |               |
| After a server interchange on a Processor Ethernet for Duplicated Servers system, <b>Communication Manager</b> could experience an extra system restart.   | 091379   |               |
| After spontaneous server interchange the 'status socket-usage' could report incorrect socket counts.   | 091383   |               |
| Under certain scenarios, if a <b>SIP</b> endpoint was placed on hold, then taken off hold, its talk path would not be restored.  | 091443   |               |
| Non-encrypted Media Gateway could not auto fall back to the main server's Processor Ethernet interface from Local Survivable Processor ( <b>LSP</b> ) or Enterprise Survivable Processor ( <b>ESS</b> ). | 091461   |               |
|  |          | <b>2 of 2</b> |

---

## Problems fixed in Communication Manager 5.2 SP #1

This release includes the following fixes delivered to **Communication Manager**.

**Table 3: Fixes delivered to Communication Manager 5.2 SP #1 1 of 3**

| Problem   | Keywords | Workaround    |
|---|----------|---------------|
| At the time of transfer recall, the transferring party showed line2 blank. To reproduce this problem the initial call should be made over <b>SIP</b> trunk and Toshiba <b>SIP</b> phones with Unicode name administered should be used. | 090914   |               |
| Server interchange with <b>SIP</b> call traffic caused a segmentation fault.  | 090931   |               |
| Station A on switch 1 called over a <b>SIP</b> trunk to station B on switch 2. If station B was a <b>SIP</b> phone and transferred the call to another <b>SIP</b> phone on switch 2 the call had no <i>talkpath</i> and was dropped.    | 091051   |               |
| <b>Communication Manager</b> did not support <b>SIP</b> messages that contained <b>SDP</b> with no media lines.   | 091123   |               |
|   |          | <b>1 of 3</b> |

Table 3: Fixes delivered to Communication Manager 5.2 SP #1 2 of 3

| Problem  | Keywords | Workaround                         |
|--|----------|------------------------------------|
| Potential system restart under high traffic with network outages and IP phone re-registrations.  | 091269   |                                    |
| Only one power supply was reported by the command 'hardware_info' and on the maintenance web page 'Display Configuration' for an S8510 server which is equipped with two power supplies.   | 091376   |                                    |
| When configuring SW dup on a server with a mix of 1GB/s and 100MB/s Ethernet cards (for example, S8720), the check to block assigning the dup link to anything less than 1GB/s Ethernet interface did not work.  | 091380   |                                    |
| In case of UPDATE being rejected by farEnd by sending 405 (Method Not Allowed), did not send UPDATE again for that dialog. Instead for target refresh sent Reinvite.   | 091434   |                                    |
| When <b>Communication Manager</b> created an outgoing INVITE message and there was no P-Charging-Vector available from an incoming INVITE, then <b>Communication Manager</b> created a P-Charging-Vector consisting of several identifiers to be unique. One of these identifiers was the own IP address. When the outgoing INVITE was routed to a public network, the <b>SBC</b> or other <b>SIP</b> entities passed on the unchanged P-Charging-Vector. By that the private IP-Address included in the P-Charging-Vector was visible in the public network even when all other private IP addresses were filtered out by the <b>SBC</b> . This MR fixes the problem by removing the IP address from the P-Charging-Vector (remaining part remains unique). | 091447   |                                    |
| When <b>ESS</b> or <b>LSP</b> was active, the trunks in IP signaling groups could sometimes show an incorrect service state of in-service/idle when they should actually be out of service.  | 091449   |                                    |
| On Duplex Main Servers, the <b>IPSI(s)</b> associated with the customer <b>LAN</b> did not come back into service after upgrading to <b>Communication Manager 5.2</b> .  | 091498   | Execute the "cnc on" BASH command. |
| Under certain circumstances involving a <b>SIP</b> call, <b>Communication Manager</b> could experience a memory-access error, possibly causing a system restart.   | 091646   |                                    |
| The system could lock up when attempting to take core files for an unexpected restart. The Avaya code was changed to prevent the lockup.   | 091647   |                                    |
| <b>2 of 3</b>  |          |                                    |

Changes delivered to Communication Manager 5.2 SP #3

Table 3: Fixes delivered to Communication Manager 5.2 SP #1 3 of 3

| Problem   | Keywords | Workaround |
|---|----------|------------|
| When using the "Configure Server -> Set Modem Interface" on a S8400 the PPP addresses were not set correctly on the Maintenance Processor Complex ( <b>MPC</b> ). Also, the "Configure MPC" (S8400) / "Configure RMB" (S8500) page did not set the "Reserved (Services Future Use)" Ethernet port <b>IP</b> addressing correctly. | 091648   |            |
| <b>Communication Manager</b> could experience a system restart with H.323 trunk administered.   | 091662   |            |
| Issue associated with the following keyword was also fixed in <b>Communication Manager 5.2 SP #1</b> :<br>091643  |          |            |
| <b>3 of 3</b>   |          |            |

## Problems fixed in Communication Manager 5.2 SP #2

This release includes the following fixes delivered to **Communication Manager**.

**Table 4: Fixes delivered to Communication Manager 5.2 SP #2 1 of 11**

| Problem  | Keywords | Workaround |
|--|----------|------------|
| <p>When a <b>Communication Manager</b> user dialed an extension on non-Avaya system using an H.323 trunk, then sometimes the call failed.</p> <p><b>Note:</b><br/>This fix, along with the fix for 091815 changes DTMF event behavior. DTMF events on IP trunks no longer default to using Q.931/H.225 INFO messages with keypad information elements to send DTMF information. With non Avaya equipment, <b>Communication Manager</b> now opens H.245, or if H.245 is already open, <b>Communication Manager</b> sends the DTMF information as an H.245 alphanumeric string or an H.245 tone event, depending on what the non Avaya equipment has advertised for capabilities. This could require administration changes in <b>Communication Manager</b>.</p> | 081214   |            |
| <p>When the Digital Loss Group field on the trunk-group form contained an inappropriate setting (for example, a digital station loss group was specified for a digital trunk group) then features like Inter-Gateway Alternate Routing did not work as expected. A warning message will now be given to the user if the values entered in the Digital Loss Group field or in the Analog Loss group are not appropriate for the administered trunk group type.</p>  | 083031   |            |
| <p>An entry could get added in the wrong sort position on the 'tandem-calling-party-num' or 'calling-party-num-conv' form and then the entry could not be removed. The error "Identifier not assigned" was displayed.</p>  | 083103   |            |
| <b>1 of 11</b>   |          |            |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 2 of 11

| Problem  | Keywords | Workaround |
|--|----------|------------|
| <p>Dial Plan Transparency (<b>DPT</b>) calls failed in the following case:</p> <p>a) Look-Ahead Routing (<b>LAR</b>) was enabled on the route pattern set up to handle DPT/IGAR trunk calls.</p> <p>b) The calling phone was a <b>DCP</b> or analog phone (that is, not H.323 or <b>SIP</b>).</p> <p>Also, both <b>IGAR</b> and <b>DPT</b> calls failed in the following case:</p> <p>a) Look-Ahead Routing (<b>LAR</b>) was enabled on the route pattern set up to handle DPT/IGAR trunk calls.</p> <p>b) The call was rerouted using a later route pattern preference, because the initial <b>DPT/IGAR</b> call failed with an <b>ISDN</b> Cause value that triggers <b>LAR</b>.</p> | 083190   |            |
| <p><b>VDN</b> override rules with <b>ASAI</b> were not applied to internal calls. This resulted in inconsistent behavior between internal and external calls when the features 'Allow <b>VDN</b> Override' and '<b>VDN</b> Override for <b>ISDN</b> Trunk <b>ASAI</b> Messages' were enabled.</p>  | 083531   |            |
| <p>Incorrect <b>DSP</b> Region measurements could be reported in the list meas ip dsp region reports.</p>  | 083649   |            |
| <p>When call was made to a Group page extension with a station Administered without Hardware as its member, then a delay of at least seven seconds was observed in getting confirmation tone.</p>  | 083691   |            |
| <p>On receiving H323 Facility Message with H.245 Socket information, Avaya <b>Communication Manager</b> opened the H.245 socket even when the facility reason was other than start H.245.</p>  | 083747   |            |
| <p>Dial Plan Transparency feature was invoked towards an unplugged IP phone causing improper trunk usage.</p>  | 083845   |            |
| <p>When EC500 set dial the idle call appearance <b>FNE</b> (Feature Name Extension) and then dialed an external number, <b>ASAI</b> did not report the called number in the Alerting and Connect events.</p>   | 090016   |            |
| <p>Both the stations in the call showed "CONFERENCE" after the transfer was completed. This problem was visible when the transferee station was not an off-PBX telephone integration &amp; mobility (<b>OPTIM</b>) station.</p>  | 090036   |            |
| <p><b>2 of 11</b></p>  |          |            |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 3 of 11

| Problem  | Keywords | Workaround |
|--|----------|------------|
| Hunt group had only one member ( <b>SIP</b> station A) and a coverage to an answer group if busy / no answer. Station A was on a call on call appearance 1. There was an incoming call to the hunt group, the problem was the call was ringing on the 2nd call appearance instead of going to the coverage answer group.   | 090123   |            |
| <b>ISDN</b> call setup retried as a result of glare conditions failed if Explicit Call Transfer or Two B-Channel Transfer supplementary service was active on the call. This error occurred only if glare happened on a call which was setup due to vector ~r route-to step.   | 090130   |            |
| Music was not played to the calling station when the Look-Ahead Interflow ( <b>LAI</b> ) checks were performed on the <b>Communication Manager</b> .   | 090140   |            |
| When the <b>PSTN</b> did not send the calling party number and the replacement string was configured for restricted numbers, the display at called party side (a station that is listed in a vector of a vector directory number) did not show the replacement string.   | 090196   |            |
| If a call to Home Enterprise Mobility User ( <b>HEMU</b> ) was answered on Visitor Enterprise Mobility User ( <b>VEMU</b> ), call pickup lamp on Home Enterprise Mobility User ( <b>HEMU</b> ) pickup group members kept flashing.   | 090209   |            |
| When call from second call appearance on <b>IP</b> station placed over <b>IP</b> trunk, which had early media and <b>AES</b> encryption enabled, the first call was fine but the second call was garbled.  | 090280   |            |
| Made a call to a station that was bridged on another station and answered the call on the bridged station. Transferred the call to another station. Call got dropped.  | 090303   |            |
| When calls were made to Vector Directory Numbers ( <b>VDN</b> ) which had <b>VDN</b> Origination of Announcement ( <b>VOA</b> ), were answered, the line four display on the station displayed "date and time" instead of "To " This problem was specific for "Avaya Digital Terminal for Japan" ( <b>J24</b> ) sets and would not be visible if "Idle Appearance Preference" field on the station form is set to "n". | 090350   |            |
| Calls did not go to the EC500 when the Media Gateway to which the desk phone was connected was unregistered.   | 090472   |            |
| <b>3 of 11</b>   |          |            |

**Table 4: Fixes delivered to Communication Manager 5.2 SP #2 4 of 11**

| Problem  | Keywords | Workaround   |
|--|----------|--|
| There was neither a ring back tone nor a voice path if vu-stat feature was active on the phone and long stream of digits was dialed to originate a call.   | 090519   | Disable vu-stat feature on the phone.  |
| In the case of a <b>SIP</b> privacy call, if the calling party number was restricted, the calling party number was not stored in the Call Detail Record.   | 090544   |  |
| The customer may see intermittent failures on backups to Compact FLASH cards on S8400 systems when the card timing was outside of the manufacturer's specifications. Timing was modified to increase the window significantly beyond the specification reducing the possibility of failures. | 090556   |  |
| As per RFC 3261, port in <b>URI</b> was disallowed for From/To header.   | 090580   |  |
| A call was made to a station A having EC500 feature enabled, this call is answered by the off-pbx extension which was mapped to station A via EC500 feature. Now when user presses any digit on this off-pbx station, caller doesn't receive <b>DTMF</b> .                                   | 090633   |  |
| This allows phones with a call appearance that is in CA_WAIT_ORIG to originate a call on that appearance. This will prevent that appearance from being stuck and considered busy by the software.  | 090655   |  |
| No incoming call log entry was made for the Expert Agent Selection ( <b>EAS</b> ) agent if that <b>EAS</b> agent's "auto answer" mode was configured to either "acd" or "all".   | 090662   | Don't configure "auto-answer" mode to "acd" or "all" for an agent with Expert Agent Selection. |
| <b>4 of 11</b>   |          |  |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 5 of 11

| Problem   | Keywords | Workaround   |
|---|----------|--|
| Faxes were failing when <b>Communication Manager</b> received a fax re-INVITE with a=inactive just prior to requesting a switch to T38 fax. Now, <b>Communication Manager</b> responds with 200 OK, a=inactive, and null IP address/port and does not begin a transition to fax until receiving a re-INVITE with a=sendrcv.                                 | 090687   | Do not send a fax re-INVITE with a=inactive prior to requesting a switch to T38 fax. |
| If a queue button was pressed on attendant immediately after dialing any single digit and continue dialing remaining digits, the displays shows digits interspersed.  | 090740   |  |
| Agent coming out of aux to take call did not get indication of <b>VDN</b> where call was in queue.  | 090742   |  |
| When a user logged into the <b>SAT</b> (System Access Terminal) through the TN799 ( <b>CLAN</b> ) board and the password had expired, the user was not prompted to change the password.   | 090745   |  |
| When "list trace vector" displays a route-to command with a collected digit of "0" or "#", the character "a" (10) or "c" (12) is actually displayed instead.  | 090750   |  |
| When <b>IP</b> phone on <b>Communication Manager</b> called <b>DECT</b> phone via <b>QSIG</b> trunk and <b>DECT</b> phone happened to be switched-off, call got dropped instead of providing any feedback to internal caller.   | 090780   |  |
| When there was a hold recall on the call and caller dropped the call, the station remained off-hook.  | 090788   |  |
| Busy out on H.323 trunks in certain intermediate call states was not allowed. The busyout command, in this case, failed.  | 090793   |  |
| Remote coverage calls were dropped if the covering station was an x-ported analog station. The problem was only seen if "Don't Answer Criteria For Logged Off <b>IP/PSA/TTI</b> Stations" was set to 'y' on page 3 of the system-parameters features form and "Maintain <b>SBA</b> At Principal?" set to 'y' on system-parameters coverage-forwarding form. | 090801   |  |
| If two or more Busy Tone Disconnect ( <b>BTD</b> ) trunks were involved in a meet-me conference, those <b>BTD</b> trunks which joined the call after the first <b>BTD</b> trunk, were not disconnected when the caller dropped.   | 090813   |  |
|   |          | <b>5 of 11</b>   |

**Table 4: Fixes delivered to Communication Manager 5.2 SP #2 6 of 11**

| Problem   | Keywords | Workaround |
|---|----------|------------|
| When administering the dialplan at the <b>SAT</b> (System Access Terminal) with certain dialplans, the customer would see the following error message when making any changes to the public-unknown-numbering form form: "Ext code inconsistent with dialplan". which would block them from making the changes they wanted to make.   | 090814   |            |
| Long hold recall alert was not working if Single Step Conference or Service Observer involves in call.  | 090818   |            |
| When a call which comes on a Vector Directory Number ( <b>VDN</b> ) was covered and went to the second coverage point when the first coverage point did not answer, with a coverage answer group as the second coverage point, the station answering the covered call displayed "c" on line four of its display instead of <b>VDN</b> name. This problem was specific to "Avaya Digital Terminal for Japan" ( <b>J24</b> ) sets.  | 090857   |            |
| This problem affects all servers. Previously, the <b>ISG</b> would crash in the pacer service software. Now, the <b>ISG</b> will verify the pointers are valid before executing the pacer service software. An error will be logged if, the <b>ISG</b> finds any invalid pointers.  | 090872   |            |
| Call progress tones may not be heard when using H.323 overlap sending/receiving trunks.   | 090876   |            |
| CallMaster V or 64xx stations did not clear the display when it was on a call with headset and transferred the call.  | 090883   |            |
| Error message was displayed after "display internal-data sta-port XXXXXX" on a <b>IP</b> station port, or H.323 <b>LAN</b> port.  | 090899   |            |
| If the <b>VEMU</b> (Visitor Enterprise Mobility User) called another station on the visitor switch and that station transfered or conferenced the call, the call was dropped after a few minutes.   | 090932   |            |
| When Call to prime is tranfered to <b>VDN/HUNT</b> , the display on transfered party was showing calling party's information.   | 091025   |            |
| When calls made to Vector Directory Number ( <b>VDN</b> ), which is routed to an Administration Without Hardware ( <b>AWOH</b> ) station, is covered to a coverage answer group, the line four display on the stations in the coverage answer group showed "c" instead of "date and time". This would occur when "Idle Appearance Preference" is enabled on the stations in the coverage answer group. This problem would be specific for "Avaya Digital Terminal for Japan" ( <b>J24</b> ) sets. | 091029   |            |
| <b>6 of 11</b>  |          |            |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 7 of 11

| Problem  | Keywords | Workaround   |
|--|----------|--|
| Abbreviated dialing having too many digits in the dialed string used to cause <b>PCD</b> (Packet Control Driver) congestion.   | 091033   |  |
| System resets can occur on <b>Communication Managers</b> using the <b>ASAI</b> feature.  | 091035   |  |
| Intermittently, certain button pushes (like serv-obs) could be incorrectly denied.   | 091065   | Remove the service observing port and add it back. |
| Under certain internal conditions <b>Communication Manager</b> slowed down during Automatic Call Distribution( <b>ACD</b> ) calls.   | 091066   |  |
| The Call Pickup feature had a special algorithm to determine which call was to be picked up next. The pickup display was updated to reflect any changes to the next call to be picked up. The display was not updating properly in case of Enhanced Call Pickup alerting.                                    | 091118   |  |
| The system restarted when an <b>ISDN BRI</b> endpoint was connected to <b>Communication Manager</b> and the endpoint sent an <b>ISDN</b> message containing an information element with an invalid length field.   | 091131   |  |
| Under certain circumstances, a softphone user in 'telecommuter' mode could hear distorted dialtone and voice when the administered "callback number" on the softphone was routed to a shuffable <b>SIP</b> trunk.  | 091149   |  |
| The "group-sel" button on the attendant console did not work. After pushing the "group-sel" button, you could not dial the group digits successfully.  | 091177   |  |
| Data for the g3trunksta <b>MIB</b> group displayed garbage values when a walk was performed on the g3mib.  | 091186   |  |
| Call Forwarded FNU INVITE failed when Fast Connect on Origination field on off-pbx-telephone configuration-set form was set to 'y'.  | 091204   |  |
| Display on bridge appearance of a 2420 digital station was not cleared when it had two bridge-appearances for two different principal stations wherein the first call was answered by the principal station and the second call to another principal station was dropped by the originator before answering. | 091215   |  |
|  |          | <b>7 of 11</b>                                     |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 8 of 11

| Problem   | Keywords | Workaround                |
|---|----------|---------------------------|
| For a <b>TSP</b> station, when the auto-call-back alert was received over a <b>SIP</b> trunk and the administered name for the calling party was Unicode, then the line-2 display was blank. This occurred always when the trunk between the 2 <b>Communication Managers</b> was a <b>SIP</b> trunk and the <b>TSP</b> stations had Native Unicode names administered.  | 091331   | Administer Name-1 values. |
| When Toshiba SIP Phone ( <b>TSP</b> )-1 called <b>TSP</b> -2 over a Session Initiation Protocol ( <b>SIP</b> ) trunk and if <b>TSP</b> -2 had call forwarded to <b>TSP</b> -3 over a <b>SIP</b> trunk, as <b>TSP</b> -3 rang, display on <b>TSP</b> -1 showed name and number of <b>TSP</b> -2 instead of <b>TSP</b> -3.  | 091332   |                           |
| When a trunk call was blind transferred over the trunk again to an Administration Without Hardware ( <b>AWOH</b> ) station, the station having the Bridge Appearance ( <b>BA</b> ) of that <b>AWOH</b> station displayed the information of the transferring party even after the transfer was complete. It should have displayed the information of the other connected party. This problem is specific for Avaya Digital Terminal for Japan ( <b>J24</b> ) stations and would only occur if the "Bridged Idle Line Preference" field on the station form is set to "y". | 091335   |                           |
| When Attendant-1 transferred the call to Attendant-2 and canceled it using 'cancel' button, Attendant-2 kept beeping though the call was canceled.  | 091349   |                           |
| During a conference call, phone display garbled if it dropped last added party which was across <b>SIP</b> trunk to other <b>Communication Manager</b> . This problem was specific to "Avaya Digital Terminal for Japan" (2420J) stations.  | 091352   |                           |
| A general check was there for sip_max_forwards, which should be only applicable for <b>SIP/OPTIM</b> originated calls.  | 091411   |                           |
| The calling party name was not displayed on the principal station in the case of an incoming <b>USNI</b> (United States Network Interface) trunk call if <b>SAC</b> (Send All Calls) was activated.   | 091416   |                           |
| Changing ping parameters on page one of the "system-parameters ip- options" form on an S8300 causes invalid TTR-LEV alarms to appear.   | 091427   |                           |
| On all the list measurements ipserver-interface [hourly summary] reports, sometimes the Up-link and Down-link Throughput values were out of range and displayed incorrect data.   | 091517   |                           |
| <b>8 of 11</b>  |          |                           |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 9 of 11

| Problem  | Keywords | Workaround   |
|--|----------|--|
| In case where <b>SAC</b> (Send-All-Calls) for remote was administered first and then <b>SAC</b> for prime, when <b>SAC</b> for prime was activated, <b>SAC LED</b> for bridge was on.  | 091527   | Administer a self- <b>SAC</b> button before remote- <b>SAC</b> button. |
| When third party Send All Calls ( <b>SAC</b> ) by a Toshiba <b>SIP</b> Phone ( <b>TSP</b> ) was denied, the primary appearance of the <b>TSP</b> was reflecting the feature denial and was getting stuck.  | 091528   |  |
| When Station A called Station B over a Distributed Communication System ( <b>DCS</b> ) trunk, and the call covered to a <b>SIP</b> Modular Messaging system over a <b>SIP</b> trunk on no-answer at Station B, Station A received a non-integrated greeting.   | 091539   |  |
| The system could lock up when attempting to take core files for an unexpected restart. The Avaya code was changed to prevent the lockup.   | 091543   |  |
| In case of call redirection, the new INVITE should have proper request <b>URI</b> , with Coverage Of Calls Redirected Off-Net enabled or disabled.   | 091549   |  |
| When using the "Configure Server -> Set Modem Interface" on a S8400 the PPP addresses aren't set correctly on the Maintenance Processor Complex ( <b>MPC</b> ) Also, the "Configure <b>MPC</b> " (S8400) / "Configure <b>RMB</b> " (S8500) page doesn't set the "Reserved (Services Future Use)" Ethernet port <b>IP</b> addressing correctly. | 091582   |  |
| When an external call was made to a Busy <b>IP DECT</b> station, caller was getting reorder tone instead of getting busy tone.   | 091586   |  |
| Under certain circumstances involving a <b>SIP</b> call, <b>Communication Manager</b> could experience a memory-access error, possibly causing a system restart.   | 091592   |  |
| <b>Communication Manager</b> could experience a system restart with H323 trunk administered.   | 091602   |  |
| For duplicated <b>Communication Manager</b> servers employing "software duplication" with an encrypted duplication link, the active server may reset when the standby server is stopped, started, reset, busied out or released.   | 091604   |  |
| <b>9 of 11</b>   |          |  |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 10 of 11

| Problem   | Keywords | Workaround |
|---|----------|------------|
| Video calls to the Polycom RSS2000 may fail in unpredictable ways; they may get no video, or simply drop. The behavior is dependent on the bandwidth requested for the call, the endpoint calling, etc. This fix is required for use of the RSS2000. Other third-party video devices may be affected if they have not been part of a development collaboration with Avaya. The Polycom <b>RMX, MGC</b> , PathNavigator, <b>CMA, HDX, VSX</b> are all unaffected; as are Codian and Cisco devices. | 091626   |            |
| Server interchanges caused by a network outage with phones connected via PROCR may lead to incorrect socket counts and failure to re-register.  | 091649   |            |
| Calls fail to conference after covering and routing from a <b>VDN</b> to a valid extension.   | 091668   |            |
| Media Gateway ( <b>MG</b> ) could get removed after the server interchange if this <b>MG</b> registered to the Processor Ethernet ( <b>PE</b> ) interface.  | 091674   |            |
| When Toshiba <b>SIP</b> Phone ( <b>TSP</b> )-1 called <b>TSP</b> -2 over a Session Initiation Protocol ( <b>SIP</b> ) trunk and if <b>TSP</b> -2 had Send-all-calls activated to <b>TSP</b> -3 over a <b>SIP</b> trunk, as <b>TSP</b> -3 rang, display on <b>TSP</b> -1 showed name and number of <b>TSP</b> -2 instead of <b>TSP</b> -3.   | 091681   |            |
| <b>IP</b> agent calls were getting dropped in certain scenarios involving high call traffic.  | 091687   |            |
| After un-parking the call, Avaya Digital Terminal for Japan ( <b>J24</b> ) station would show feature access code ( <b>FAC</b> ) along with the station's number for which it was un-parking the call. This was happening intermittently.   | 091695   |            |
| For <b>Communication Manager</b> systems utilizing H.248 gateways and an Application Enablement Server, outgoing calls generated via <b>AES</b> failed.   | 091697   |            |
| An unexpected reset of MAIN server from running <b>SAT</b> command ' <b>disable ess all</b> ' or ' <b>disable ess cluster 1</b> ' would occur if the main server was controlling only Media Gateways but no <b>IPSI</b> port networks.  | 091716   |            |
| After a server interchange some phones registered to the Processor Ethernet could not get dial tone.  | 091753   |            |
| On S8300D servers running <b>Communication Manager</b> and <b>SIP</b> Enablement Services ( <b>SES</b> ) co-resident, Provision could not create 450 <b>SIP</b> users in <b>SIP</b> Enablement Services.  | 091773   |            |
| <b>10 of 11</b>   |          |            |

Table 4: Fixes delivered to Communication Manager 5.2 SP #2 11 of 11

| Problem  | Keywords | Workaround      |
|--|----------|-----------------|
| Neither a History-Info header nor a <b>SIP</b> Diversion header was created for <b>VDN</b> redirections for the "route-to number" step (with or without coverage) and the "route-to number" step where the number has ~r for network call redirection. | 091870   |                 |
| Issues associated with the following keywords were also corrected in <b>Communication Manager</b> 5.2 SP #2:<br>091273, 091289, 091516, 091551, 091671, 091701   |          |                 |
|  |          | <b>11 of 11</b> |

---

## Problems fixed in Communication Manager 5.2 SP #2.01

This release includes the following fixes delivered to **Communication Manager**.

Table 5: Fixes delivered to Communication Manager 5.2 SP #2.01

| Problem   | Keywords         | Workaround |
|---|------------------|------------|
| <p>An Avaya <b>Communication Manager</b> user could not login on the IA770 to retrieve voice messages.</p> <p><b>Note:</b><br/>This fix, along with the fix for 081214 changes DTMF event behavior. DTMF events on IP trunks no longer default to using Q.931/H.225 INFO messages with keypad information elements to send DTMF information. With non Avaya equipment, <b>Communication Manager</b> now opens H.245, or if H.245 is already open, <b>Communication Manager</b> sends the DTMF information as an H.245 alphanumeric string or an H.245 tone event, depending on what the non Avaya equipment has advertised for capabilities. This could require administration changes in <b>Communication Manager</b>.</p> | 091815<br>092571 |            |
|   |                  |            |

## Problems fixed in Communication Manager 5.2 SP #3

This release includes the following fixes delivered to **Communication Manager**.

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 1 of 12**

| Problem  | Keywords | Workaround   |
|--|----------|--|
| Sometimes the <code>list measurements blockage pn today-peak/yesterday-peak/last-hour</code> command showed incorrect data for 'Time Division Multiplexed (TDM) Usage' while running on a idle switch.   | 073919   |  |
| A customer had an Octel Voicemail adjunct in the coverage path and a station A on switch A that had its calls forwarded to station B on switch B heard both ring back tone as well as Voice mail greeting if the two switches were connected over a <b>QSIG</b> trunk and had <b>QSIG VALU</b> set to yes.   | 081964   | Turn off the <b>QSIG VALU</b> field.   |
| If Redirect on OPTIM Failure (ROOF) occurred for a call to a non- <b>ACD</b> hunt group, the <b>Communication Manager</b> server was going into overload.  | 083527   |  |
| <b>PSA</b> users were being blocked and denial event 1098 (TTI merge/unmerge failed) was being seen when the customer failed to complete the <code>duplicate station</code> or <code>duplicate agent-loginID</code> commands at the <b>SAT</b> (System Access Terminal). The <b>SAT</b> was displaying the list output of the stations or agents it added after the submit key was pressed. If the "Next Page" key or "Cancel" key was not pressed to complete the command, <b>PSA</b> users would be blocked. | 090616   | Complete the list of <code>duplicate station</code> or <code>duplicate agent-loginID</code> commands by either pressing the "Next Page" key or canceling the command using the "Cancel" key. |
| If a call-center agent using an H.323 endpoint or softphone was offered a call, but their endpoint was not configured to support a compatible audio codec (per the ip-codec-set admin forms), the call could not be connected, and it would not be offered to any other agent (possibly resulting in a <code>calls in queue, agents available</code> condition).   | 090668   |  |
| Leave word calling did not work for mixed length dial-plan connected via <b>DCS</b> trunk.   | 090683   |  |
| <b>1 of 12</b>   |          |  |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 2 of 12

| Problem  | Keywords | Workaround     |
|--|----------|----------------|
| When an Avaya H.323 <b>IP</b> phone called over an H.323 <b>IP</b> trunk to a Cisco phone controlled by a Cisco Call/UC Manager, and the Cisco phone then put the call on hold, music-on-hold was successfully applied by the Cisco end and heard by the Avaya phone. When the Cisco phone unheld the call, talkpath was not restored.   | 090823   |                |
| For 4624 <b>IP</b> sets, the firmware release field on the "status station " and "list registered ip-stations" forms was not correct.  | 090965   |                |
| A team button was configured for a station. A call is picked using this team button. Transfer of this call to the voice mail server failed.  | 091009   |                |
| Abbreviated dialing containing ~w fails where dialing string contained remote access extension and authorization codes in it.  | 091032   |                |
| <b>SIP</b> service link did not shuffle back to direct <b>IP</b> after agent unhold a call.  | 091040   |                |
| Previously, there were race conditions where the drop of a domain controlled party occurred between the alerting of a second domain controlled party and the connection of the second domain controlled party that caused the <b>Communication Manager</b> to fail to respond to certain 3PCC commands from the adjunct application. Now, if a domain controlled party drops at any time it will be handled properly and <b>Communication Manager</b> will continue to respond to 3PCC commands. | 091044   |                |
|  |          | <b>2 of 12</b> |

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 3 of 12**

| Problem   | Keywords | Workaround |
|---|----------|------------|
| <p>Calling/called parties heard an unexpected beep after the call was answered in the following cases:</p> <ul style="list-style-type: none"> <li>- Called a vector that routed to a variable-length <b>AAR/ARS</b> number.</li> <li>- If vector step had cov=y, worked fine with no beep.</li> <li>- If vector step had cov=n, heard a beep.</li> </ul> <p><b>Note:</b><br/>A few customers may have entered a final # in route-to-number steps to keep the step from hanging if the route-to-number was variable length (for example, the <b>AAR / ARS</b> minimum length was less than the maximum length). With this MR change, this final # is no longer needed, and will result in a "beep" played after the call is answered. Any customer with a final # in a route-to-number step should remove it after getting this MR change.</p> | 091247   |            |
| <p>If call was answered on Bridge Appearance (<b>BA</b>) and call park button was pressed twice on that station (<b>BA</b>), call appearance button LED on that <b>BA</b> remained ON indefinitely.</p>   | 091333   |            |
| <p>DID/Tie/<b>ISDN/SIP</b> Intercept to Announcement was failing with Separation of Bearer and Signaling (<b>SBS</b>) trunks when the caller mis-dialed the number.</p>   | 091338   |            |
| <p>When EC500 user dialed the idle call appearance <b>FNE</b> (Feature Name Extension) and then dialed an external number, <b>ASAI</b> reported an incomplete called number in the Alerting and Connected events if,</p> <ul style="list-style-type: none"> <li>- the Digit Handling field on the trunk group form was set to "overlap/overlap".</li> <li>- the field "DTMF over IP" on the H.323 signaling group form was set to "in-band".</li> <li>- the user dialed the digits very slowly.</li> </ul>  | 091395   |            |
| <p>When the NICE recording application was used and network disruptions caused media gateways to lose connectivity with the <b>Communication Manager</b> server, stations being recorded were left in an Out-of-Service state after the gateways re-registered with <b>Communication Manager</b>.</p>   | 091439   |            |
| <b>3 of 12</b>  |          |            |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 4 of 12

| Problem  | Keywords | Workaround |
|--|----------|------------|
| The customer may experience dropped calls or no <i>talkpath</i> after issuing a <b>reset media-gateway</b> level one or level three command and the H.248 media gateway was re-registered (for a level one reset) or the H.248 media gateway modules were back in service (for a level three reset).   | 091442   |            |
| <b>PAM</b> security traps were missing logname, uid, euid, tty ruser, rhost, and user information after the FPAgent processed them. The complete trap was displayed in the messages file located in /var/log/messages.   | 091480   |            |
| If an H.323 IP station or a <b>DCP</b> station dialed into an Expanded Meet-Me Conferencing Vector Directory Number which routed over H.323 or <b>SIP</b> trunks to an external conference bridge, then the party entering the conference did not get cut through to the rest of the conference.   | 091511   |            |
| When an <b>ESS</b> became active due to network fragmentation, causing calls between the main and the <b>ESS</b> to use the dial-plan transparency feature, some calls to or from the <b>ESS</b> location could have experienced a lack of <i>talkpath</i> if the <b>ESS</b> happened to be controlling a port network configured with DS1 trunks. | 091570   |            |
| <b>IQ/CMS</b> could abort tracking of calls deflected between <b>Communication Manager</b> servers by Network Call Redirection ( <b>NCR</b> ) on <b>SIP</b> trunks.  | 091573   |            |
| Avaya Voice Portal ( <b>AVP</b> ) endpoints were not getting registered when there were no signaling resources in the connected network regions.   | 091593   |            |
| Conditions:<br>a) An <b>ASAI</b> adjunct initiated a call to an OOS station on the same server but in a different Network Region.<br>b) The call invoked Dial Plan Transparency to reach the OOS station.<br>c) The <b>ASAI</b> adjunct dropped the call early, before the call was set up.<br>The above case led to a system restart.             | 091655   |            |
| An example file and directory indicated in a logging man page for configuring views were not clearly identified as an example, causing users to think they actually existed on the server.   | 091666   |            |
| <b>4 of 12</b>   |          |            |

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 5 of 12**

| <b>Problem</b>   | <b>Keywords</b>  | <b>Workaround</b>                              |
|--|------------------|--|
| The voicemail adjunct reported the wrong calling party number in some "transfer to voicemail" scenarios involving X-ported stations.   | 091670           |  |
| In the case of an H.323 <b>IP</b> station with three button modules, one bridge call appearance was configured on the third button module. Then that bridge call appearance was moved to the first button module. When a call was made to that bridge call appearance extension, a blank display was seen and also the call log showed as unavailable. | 091692           |  |
| When EC500 State was disabled using station form for a station with off-pbx-telephone station-mapping for EC500 application, the first attempt to enable the EC500 using the EC500 button failed. The feature was deactivated again instead of being activated. Pushing the EC500 button again activated the EC500 feature.                            | 091743           | Push the button again to activate the feature. |
| Bridged calls answered by Extended to Cellular (EC500) could not be service observed   | 091745           |  |
| Incoming <b>SIP</b> calls from some non-Avaya systems may fail.  | 091747           |  |
| After 96xx <b>IP</b> station A took over the extension for another 96xx <b>IP</b> station B, and then station B takes back the extension from station A and then the process was repeated a few times, both stations could end up in a locked up state.  | 091754           |  |
| Second page of the duplicate station form failed to open when duplicating XMOBILE station with Mobility Trunk Group of 'ars' and 'aar', Also, duplicate XMOBILE stations failed intermittently with Mobility Trunk Group set to a trunk group number.  | 091766           |  |
| Under circumstances pertaining to a specific method of <b>SIP</b> signaling, calls over a <b>SIP</b> trunk connected to a Service Provider dropped.  | 091777           |  |
| After a server interchange, <b>Communication Manager</b> could experience an extra system restart.   | 091783           |  |
| Under certain internal conditions, the system may reset during normal call operation.  | 091784<br>091785 |  |
| Under certain internal conditions, <b>Communication Manager</b> may reset, impacting call processing.  | 091786           |  |
| <b>5 of 12</b>   |                  |  |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 6 of 12

| Problem   | Keywords | Workaround |
|---|----------|------------|
| For an external call coming over an <b>ISDN</b> trunk to a local station on Communication Manager, an <b>ASAI</b> call recording application would shut down and do a server interchange when the called station was incorrectly identified as "National" instead of "private local number" in the Alerting event.  | 091796   |            |
| Customers monitoring stations with <b>ASAI</b> may see a # sign at the end of the Called party number when user classified calls were placed using <b>TAC</b> dialing.  | 091797   |            |
| TN2602 Medpro alarms were incorrectly generated on an <b>LSP</b> after the <b>LSP</b> was upgraded.   | 091800   |            |
| Native Administered 96xx phone A was in a conference call with phone B and phone C. Then phone A pushed the transfer button to dial phone D, D rang. Then phone B dropped from the conference call, and phone A cancelled the transfer call. At this time, phone A could not go back to talk with phone C.  | 091807   |            |
| A user was allowed to press a pickup-group button to pickup a call of a fellow pickup-group member, when that group member was listening to a <b>VDN</b> of Origin Announcement ( <b>VOA</b> ) for a Vector Directory Number ( <b>VDN</b> ). That resulted in a situation where the user did hear the <b>VOA</b> , but, when connected to the caller, did not have <i>talkpath</i> (and the party who originally answered was dropped). | 091811   |            |
| All the <b>IP</b> stations on the server were abruptly rebooting at the same time.  | 091818   |            |
| When the 'ANALOG BUSY AUTO CALLBACK Without Flash?' field was enabled on system-parameters features form, 'Busy Auto Callback without Flash?' field did not appear on station form for callrID stations.  | 091819   |            |
| When an attendant vector had two queue-to attendant/ attd-grp steps and the first one failed, a spurious "forward" event was reported to <b>IQ/CMS</b> . This could result in the appearance of calls-in-queue with agents available.   | 091862   |            |
| A <b>SIP</b> phone with a call from a phone on a gateway that was on hold, could not be unheld and the call was soon dropped.   | 091863   |            |
| <b>6 of 12</b>  |          |            |

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 7 of 12**

| Problem   | Keywords | Workaround |
|---|----------|------------|
| Customers with a feature access code administered on their switch for PIN Checking for Private Calls Using <b>ARS</b> Access Code or PIN Checking for Private Calls Using <b>AAR</b> Access Code could not register <b>IP</b> H.323 virtual endpoints (that is, <b>IP</b> Softphone, <b>IP</b> Agent).  | 091880   |            |
| When the station on a call dialed the announcement extension after pressing the no hold conference button, three party conference did not proceed & the phone display showed <code>Connecting to 403</code> , where 403 was the announcement extension.   | 091885   |            |
| Executing a <code>list trace hunt-group</code> command for an Audix hunt group failed to output any records when calls terminated to the group.   | 091896   |            |
| There should not be any core even when the called Number is NULL.   | 091900   |            |
| Port change in 200 OK against display reinvoke or session refresh reinvoke caused <i>talkpath</i> break or call drop.   | 091923   |            |
| The call transfer destination station was showing transferring station's information as connected party information after call was transferred. This problem was observed on 64xx phone only with headset button turned ON.   | 091926   |            |
| In case of Calling ID blocking, cellular service provider originated call from mobile phone was not working.  | 091936   |            |
| When vu-display was enabled and an external call landed on an <b>IP</b> station, the starting part of the display on the call appearance button was truncated. This happened for <b>IP</b> stations like 4610, 4620, 4621, 4622, 4625, 9620, 9630, 9640, 9650, 1608, 1616 which display the incoming/outgoing name and extension on the call appearance, only when the VuStats feature was enabled. | 091953   |            |
| When the switch had a 2 port network setup and we did call pick up or call unpark the <i>talkpath</i> should be there. If shuffling was enabled, then the call went to direct <b>IP</b> .   | 091976   |            |
| <b>7 of 12</b>  |          |            |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 8 of 12

| Problem   | Keywords | Workaround   |
|---|----------|--|
| <p>Preconditions for the error were:</p> <p>There was a hunt group with two stations `A` and `B` as members. Both members of the hunt group had a team button configured:</p> <ul style="list-style-type: none"> <li>- Station `A` had a team button which pointed to station `B`</li> <li>- Station `B` had a team button which pointed to station `A`.</li> </ul> <p>The setting of the feature "Temporary Bridged Appearance on Call Pickup" on page 18 on the "system-parameters features" form must be set to "n".</p> <p>When the hunt group extension was called from a third station then either `A` or `B` was ringing.</p> <p>In the same time the team button started blinking on the station which was NOT ringing. After pushing team-button twice (!) on this non-ringing station the call was picked-up, but the team-button kept blinking. Even after the call was ended.</p> | 091977   | Avoid the error: The team button is working properly, when the feature "Temporary Bridged Appearance on Call Pickup" on page 18 on the "system-parameters features"-form is enabled. |
| Port number shall not be sent as 0 in From header for a <b>SIP</b> tandem call scenario   | 091985   |  |
| Avaya Site Administration "Export" vector failed to provide "skill" value for pages 2-6 with vector steps: -"check skill", -"consider skill", -"goto .. if expected-wait for skill"- "goto .. if rolling-asa for skill" " The exported text file contained no value for the fields containing "skill".  | 091990   |  |
| If a H.323 station outgoing direct media call was made to a non-Definity <b>Communication Manager</b> , then call got dropped.  | 092002   |  |
| When a call from <b>PSTN</b> was transferred to an unregistered station, which was connected to Modular Messaging via <b>SIP</b> trunk, a general greeting was played.  | 092003   |  |
| Modifying a <b>SMI</b> user profiles name to contain one of the characters '&' and '<' led to make this profile unreadable. This effect could also occur during an upgrade, if one of the existing user profile names contained one of these characters.  | 092009   |  |
| Calls directed to an <b>IP</b> Agent with auto answer enabled were being dropped.   | 092023   |  |
| An attendant transferring a call back to the original called <b>IP</b> phone resulted in no <i>talkpath</i> between caller and transferred to station.  | 092031   |  |
| <b>8 of 12</b>  |          |  |

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 9 of 12**

| Problem  | Keywords         | Workaround |
|--|------------------|------------|
| <b>SDES SRTP</b> call did not work across <b>SIP</b> trunk.  | 092047           |            |
| Analog media modules were receiving inconsistent downlink messages. Customer saw constantly increasing errors<br>MG_ANA 3840.  | 092056           |            |
| For an agent in auto-answer mode, after the <b>VDN</b> (Vector Directory Number) of Origin Announcement ( <b>VOA</b> ) played and the call connected, the call timer did not start. This occurred always when there was an incoming call to a <b>VDN</b> that had a <b>VOA</b> and the call routed to an agent that was logged onto a 46xx or 96xx series station.   | 092063           |            |
| Using the list trace TAC command to trace a trunk call that was added to a conference call and then later dropped fails to record the next trunk call for the trunk group. The user must exit and re-execute the command to trace another call.  | 092067           |            |
| Whenever a call was forwarded to a Vector Directory Number ( <b>VDN</b> ), which was routed to an Administration Without Hardware ( <b>AWOH</b> ) Station (P1), the display on the line four of the station having the Bridge Appearance of the <b>AWOH</b> station showed "To P1" instead of "To <b>VDN</b> ". This problem was specific to "Avaya Digital Terminal for Japan" (2420J) stations.                | 092093<br>092095 |            |
| Whenever a call from <b>PSTN</b> was covered to a Vector Directory Number ( <b>VDN</b> ), which was routed to an Administration Without Hardware ( <b>AWOH</b> ) Station (P1), the display on the line four of the station having the Bridge Appearance of the <b>AWOH</b> station showed "To P1" instead of "To <b>VDN</b> ". This problem was specific to "Avaya Digital Terminal for Japan" (2420J) stations. | 092096           |            |
| In certain circumstances, calls originating on a TOSHIBA <b>SIP</b> phone did not get proper display updates on the caller's set when the call was forwarded.  | 092114           |            |
| Vector "route-to" an <b>ARS/AAR FAC</b> suspended vector processing.   | 092125           |            |
| A H.323 trunk call between <b>Communication Manager</b> and Media Module could cause a seg fault if Media Module replied with zero codec information in faststart reply.   | 092139           |            |
| Sending out the INVITE with the "P-Charging-Vector" header (with icid-value only) even though "IMS Enabled" was turned off, was causing call failure.  | 092142           |            |
| <b>9 of 12</b>   |                  |            |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 10 of 12

| Problem  | Keywords | Workaround      |
|--|----------|-----------------|
| When a call consisted of two <b>IP</b> phones that were directly connected and one station hit hold, the resulting announcement as Music-On-Hold would be sourced based on the initial network region of the first party that initiated the call and not the remaining party that was listening to Music-On-Hold. This could cause additional <b>IP</b> resources to be allocated when listening to the <b>MOH</b> .                                       | 092169   |                 |
| On <b>SIP</b> 96xx phone auto callback button's LED used to remain ON in case of outgoing call was made on a trunk and then tried to invoke auto callback feature.   | 092176   |                 |
| When call was placed from a <b>SIP</b> originating station to a <b>SIP</b> terminating station, the call first went to <b>TDM</b> and then <b>Communication Manager</b> shuffled the call to connect direct <b>IP</b> . While Shuffling <b>Communication Manager</b> sent null INVITE to both the end points wherein if one of the end point responded with Request pending (491), then the call should not be dropped and should go to direct <b>IP</b> . | 092180   |                 |
| An attendant transferring a call back to the <b>IP</b> phone originally called resulted in no alerting on a bridged <b>IP</b> phone when Inter-Gateway Alternate Routing ( <b>IGAR</b> ) was triggered between the network region of originally called <b>IP</b> phone and the network region of the attendant.  | 092181   |                 |
| The entire call was dropped when Integrated Music On Hold was being played and Single Step Conference party hung up the call.  | 092192   |                 |
| When the user changed the node-name of a disabled <b>CLAN</b> ip-interface, the associated Link information was not updated. This eventually caused two <b>CLANs</b> to have the same <b>IP</b> address, which caused phones not to register.  | 092195   |                 |
| Under certain circumstances a call between two Motorola phones failed.   | 092214   |                 |
| Duplicated TN2602 (Crossfire) Media Processor boards were not getting sent a 'state of health' update from <b>Communication Manager</b> . This could lead to the incorrect board of the pair being active.   | 092220   |                 |
| INTERCEPT tone was not played after the timeout interval when an authorization code was required on a trunk and the user did not enter the authorization code.   | 092227   |                 |
|  |          | <b>10 of 12</b> |

**Table 6: Fixes delivered to Communication Manager 5.2 SP #3 11 of 12**

| Problem  | Keywords | Workaround |
|--|----------|------------|
| User couldn't change 2 different Vector Directory Number ( <b>VDN</b> )/hunt group's simultaneously when both <b>VDN</b> 's/hunt group's share same Computer Telephony Integration ( <b>CTI</b> ) link.  | 092235   |            |
| Station A which covered to a SIP integrated Modular Messaging voice mail adjunct. If station A received a call over a trunk and the call covered to voice mail, then the call was not covering to the voice mailbox of Station A.  | 092249   |            |
| Enable synchronization and disable synchronization commands always returned the following error Identifier command word(s) omitted; please press HELP.   | 092251   |            |
| <b>SAT</b> login IDs that have specific vectors administered in their extended-user-profile were unable to see all assigned vectors when using the <code>list vector</code> command.   | 092259   |            |
| The country-to/from information was incorrect in <b>CDR</b> reports for calls made with the Multi-National Location feature enabled.   | 092273   |            |
| <b>SIP</b> phones connected to a Connection Manager with an extended numbering environment (public numbering or private numbering enabled) may encounter some unexpected behavior. These issues may be caused by a new parameter "avext" which is included in some <b>SIP</b> messages but only valid in an Avaya Aura™ environment. | 092319   |            |
| On rare occasions, the Time Slot Record Audit ( <b>TSRA</b> ) may provide some faulty data as shown on the 'status audits cumulative' form.  | 092322   |            |
| If an outgoing R2MFC trunk call was transferred internally, the transfer failed.   | 092363   |            |
| After an R2MFC trunk call was established, if the originator pressed any digit, the <b>DTMF</b> tone was not heard at the far end.   | 092364   |            |
| Incoming <b>SIP</b> INVITE messages that contained a Replaces header sometimes resulted in failed calls.   | 092382   |            |
| Under certain <b>SIP</b> traffic conditions where network errors occurred, <b>Communication Manager</b> experienced a reset.   | 092422   |            |
| When an incoming call was transferred by an agent using a third party application over a <b>SIP</b> trunk, which had <b>NCR</b> (Network coverage redirection) enabled, the Agent application should not fail.   | 092477   |            |
| <b>11 of 12</b>  |          |            |

Table 6: Fixes delivered to Communication Manager 5.2 SP #3 12 of 12

| Problem  | Keywords | Workaround      |
|--|----------|-----------------|
| Messaging Vector step did not deactivate vector processing. As a result, any call queued to huntgroups/skills prior to the messaging step queued until the caller was disconnected.  | 092590   |                 |
| When MultiSite Administration user attempted to execute a "duplicate station" operation, an internal system error occurred and the operation failed.   | 092757   |                 |
| Defensive fix for <b>SIP</b> Timer Expiry in case of network outage.   | 092770   |                 |
| After receiving <b>DTMF</b> tones embedded into an incoming <b>RTP</b> streams, <b>Communication Manager</b> did not forward these <b>DTMF</b> tones over a H.323 trunk.   | 092775   |                 |
| Wrong station heard <b>DTMF</b> tones when call was initiated using autodial button with ~p and <b>DTMF</b> digits.  | 092835   |                 |
| If music or an end-to-end signal (for example, button press) was added to a direct <b>IP</b> call, then under certain circumstances, neither the music nor the signal would be heard.  | 092880   |                 |
| When a call is placed over <b>SIP</b> (session initiation protocol) there should be <i>talkpath</i> irrespective of the phone type from which or to which the call is placed and also the call should go to direct <b>IP</b> . | 092883   |                 |
| <b>SIP</b> transfer call involving multiple port network or gateway should have <i>talkpath</i> . It should no way depend on the type of phone to which the transfer was made, from which the transfer was done.               | 093036   |                 |
| Issues associated with the following keywords were also corrected in <b>Communication Manager</b> 5.2 SP #3:<br>073528, 081948, 091469, 091577, 091756, 091828, 092079, 092193, 092232.  |          |                 |
|  |          | <b>12 of 12</b> |

## Known problems

This release includes the following known issues in **Communication Manager**.

**Table 7: Known problems in Communication Manager 5.2 SP #3 1 of 7**

| Problem  | Keywords | Workaround   |
|--|----------|--|
| <p>If the user, from the local phone application, has customized some of their button labels on their EU24 expansion module, and the administrator changes the station type to another station type that supports both customized button labels and an EU24/expansion module, then after the change any customized button labels on the EU24 are deleted and replaced with the default button label for the given button type.</p> <p><b>Note:</b><br/>The custom labels on the primary set/main module are not deleted.</p> | 083112   | Do not change station type on stations using EU24/expansion modules. |
| <p>S8300 platforms do not currently support the <code>list meas ip dsp region</code> and <code>list meas ip dsp gw</code> commands.</p>  | 091220   |  |
| <b>1 of 7</b>  |          |  |

Table 7: Known problems in Communication Manager 5.2 SP #3 2 of 7

| Problem  | Keywords | Workaround   |
|--|----------|--|
| <p>When using web administration tools with <b>Communication Manager</b>, if the user switches between servers running different releases and/or loads, in some cases the web pages cannot be displayed or are incorrect. This is especially true when going backwards in releases (for example from <b>Communication Manager 4.1 on Server 1 to Communication Manager 3.0 on Server 2</b>).</p> | NA       | <p>Perform the following steps to clear the web browser cache on the computer:</p> <ol style="list-style-type: none"> <li>1. Open the Internet Explorer browser, and select <b>Tools &gt; Internet Options</b>.</li> <li>2. In the Temporary Internet files section, click <b>Delete Cookies</b>.</li> <li>3. Click <b>OK</b>.</li> <li>4. In the Temporary Internet files section, click <b>Delete Files</b>.</li> <li>5. Click <b>OK</b>.</li> <li>6. In the History section, click <b>Clear History</b>.</li> <li>7. Click <b>Yes</b>.</li> </ol> |
| <b>2 of 7</b>  |          |  |

**Table 7: Known problems in Communication Manager 5.2 SP #3 3 of 7**

| Problem  | Keywords  | Workaround  |
|--|-----------|---|
| <p>S8400 can be used as an Enterprise Survivable Server (<b>ESS</b>) with specific limitations. These limitations apply to both the main server and the S8400 <b>ESS</b> as shown below. These limits are not enforced by <b>Communication Manager</b> software.</p> <p>The sum of the following three components must not be greater than 1500:</p> <ol style="list-style-type: none"> <li>1. The number of H.323 Signaling Groups administered on the main server.</li> <li>2. The number of H.323 Trunk members administered on the main server.</li> <li>3. The number of H.323 <b>IP</b> endpoints that will register with the S8400 <b>ESS</b>.</li> </ol> <p>The total number of H.323 <b>IP</b> endpoints on the system can be larger than the number that will register with the S8400 <b>ESS</b> as long as the above limits are met.</p> <p>If the above limits are exceeded and the S8400 <b>ESS</b> goes active, it will not be able to register all the <b>IP</b> endpoints. The H.323 Signaling Groups and the H.323 Trunk members will first use the administered number of "IP User Records" from the pool of 1500. Any remaining <b>IP</b> User Records will be used for registering <b>IP</b> endpoints. For example, if the main server has a total of 1000 H.323 Signaling Groups and Trunk members, then 500 <b>IP</b> stations can register with the S8400 <b>ESS</b>. The main server will not experience any limitations due to the S8400 <b>ESS</b>.</p> | <p>NA</p> | <p>Use S85xx simplex servers or S87xx server pairs as <b>ESS</b> servers on larger systems.</p> |
| <p><b>3 of 7</b></p>   |           |   |

Table 7: Known problems in Communication Manager 5.2 SP #3 4 of 7

| Problem   | Keywords | Workaround |
|---|----------|------------|
| <p>Systems with duplicated S87xx main servers and TN2312 (<b>IPSI</b>) circuit packs on a customer or corporate <b>LAN</b> instead of a private network may lose communication with the <b>IPSIs</b> after an upgrade to <b>Communication Manager 5.2</b>.</p> <p>Systems with <b>IPSIs</b> on a corporate <b>LAN</b> and S87xx duplicated main servers must have Control Network C (<b>CNC</b>) configured prior to the upgrade to <b>Communication Manager 5.2</b> to avoid <b>IPSI</b> communication problems. Enabling <b>CNC</b> after the upgrade will also restore communication to the <b>IPSIs</b>.</p> <p>To check status and enable <b>CNC</b> use the following bash commands. These commands can be run by susers group logins such as "craft," "init," "dadmin," or customer defined susers group logins.</p> <p><b>cnc status</b><br/>Control Network C has NOT been configured.</p> <p><b>cnc on</b><br/>Control Network C has been configured.</p> | NA       |            |
| <p>With <b>Communication Manager 5.2</b> the administration of the route calls to agents by skill level preference on the check step can not be done using Avaya <b>CMS</b> vector administration (R15 or earlier). <b>Communication Manager</b> administration will be required to add check steps with the pref-level parameter and any vectors that contain these steps can not be accessed by <b>CMS</b> vector administration.</p>   | NA       |            |
| <p>When the feature access code for PIN Checking for Private Calls Using <b>ARS</b> Access Code is used, the external trunk is not seized and the external extension cannot be reached.</p>   | 091484   |            |
| <b>4 of 7</b>   |          |            |

**Table 7: Known problems in Communication Manager 5.2 SP #3 5 of 7**

| Problem   | Keywords | Workaround  |
|---|----------|---|
| Terminal servers used for <b>CDR</b> that are connected to duplicated S87xx servers via Processor Ethernet may lose connectivity after a server interchange. The <b>TCP</b> software in the terminal servers may not close the socket to the previously active server and open a new socket to the newly active server.         | NA       | Use the Avaya Reliable Data Transport Tool ( <b>RDTT</b> ) available at the Avaya Support web site.   |
| Customers cannot enable the Simple Voice Network Statistics ( <b>SVNS</b> ) feature for a duplicated TN2602 (Crossfire) pair when the standby Crossfire is administered in the "meas-slection" form. In this case the following error is displayed:<br>Meas-selection form is not in sync for Voice/Network Statistics feature. | 091377   | <ol style="list-style-type: none"> <li>1. Enable the <b>SVNS</b> feature in the "system-parameters ip-options" form: Enable Voice/Network Stats = y</li> <li>2. Determine which Crossfire board is the active board: status media-processor board &lt;dup_Crossfire_board&gt;</li> <li>3. Administer the "active" board in the "meas-selection media-processor" form: change meas-selection media-processor</li> <li>4. Once the active board is entered in the meas-selection form, the feature can be enabled for the dup Crossfire pair on Page 4 of the ip-interface form.</li> </ol> |
| An upgrade from S8710 configurations with <b>Communication Manager 2.2</b> , 2.2.1, 2.2.2, 3.0 or 3.0.1 to <b>Communication Manager 5.2</b> will fail.  | 091522   | Prior to the upgrade obtain, install, and activate the pre-upgrade installation patch appropriate for your <b>Communication Manager</b> release. The pre-upgrade installation patches can be found at <a href="http://support.avaya.com">http://support.avaya.com</a> .   |
| <b>5 of 7</b>   |          |   |

Table 7: Known problems in Communication Manager 5.2 SP #3 6 of 7

| Problem   | Keywords | Workaround   |
|---|----------|--|
| <p>The Branch Gateway Customer install script associated with the branch Gateway Firmware load 29.22.3 will not provision the G250 Ethernet port and G350 MM314/MM316 ports and the chassis Ethernet <b>LAN</b> port into the customer <b>VLAN</b> provisioned by the script. Follow the workaround to finish the provisioning on the platform.</p> <p>This problem is resolved in Gateway Firmware Load 29.23.0 and greater.</p> | 090271   | <p>G350</p> <ol style="list-style-type: none"> <li>1. Login to the <b>CLI</b> using the “root” login and new password provisioned using the script.</li> <li>2. Enter the command: <b>set port vlan &lt;vlan number&gt;10/3</b></li> <li>3. If an MM314 is present, enter the command: <b>set port vlan &lt;vlan number&gt; 6/1-24</b></li> <li>4. If an MM316 is present, enter the command: <b>set port vlan &lt;vlan number&gt; 6/1-40</b></li> <li>5. To save the new configuration options programmed, enter the command: <b>copy running-config startup-config</b></li> <li>6. The above has now provisioned all the G350 Ethernet ports into the new vlan and the configuration is saved.</li> </ol> <p>G250</p> <ol style="list-style-type: none"> <li>1. Login to the <b>CLI</b> using the “root” login and new password provisioned using the script.</li> <li>2. Enter the command: <b>set port vlan &lt;vlan number&gt;10/3-10</b></li> <li>3. To save the new configuration options programmed, enter the command: <b>copy running-config startup-config</b></li> <li>4. The above has now provisioned all the G250 Ethernet ports into the new vlan and the configuration is saved.</li> </ol> |
| <b>6 of 7</b>   |          |  |

**Table 7: Known problems in Communication Manager 5.2 SP #3 7 of 7**

| Problem   | Keywords      | Workaround  |
|---|---------------|---|
| <p>When a <b>USB</b> Modem Dial-In connection to a G430 is up and <b>CPU</b> utilization is high, the dial-in session might disconnect and further attempts to setup a new dial-in connection all fail. The dial-in session failure usually happens a few hours after the connection was setup. The time until the dial-in session failure depends on the <b>CPU</b> load. At 100% <b>CPU</b> utilization, the failure occurs within 1 or 2 hours. At 30% <b>CPU</b> utilization, this issue is much less frequent.</p> | <p>090291</p> | <p>If the dial-in session disconnects and cannot be setup again, unplug the <b>USB</b> modem device from of the G430 gateway and reinsert it.</p> |
| <p><b>7 of 7</b></p>  |               |   |

# Technical Support

Support for Communication Manager is available through Avaya Technical Support.

If you encounter trouble with Communication Manager:

1. Retry the action. Follow the instructions in written or online documentation carefully.
2. Check the documentation that came with your hardware for maintenance or hardware-related problems.
3. Note the sequence of events that led to the problem and the exact messages displayed. Have the Avaya documentation available.
4. If you continue to have a problem, contact Avaya Technical Support by:
  - Logging on to the Avaya Technical Support Web site <http://www.avaya.com/support>
  - Calling or faxing Avaya Technical Support at one of the telephone numbers in the [Support Directory](#) listings on the Avaya support Web site.

You may be asked to email one or more files to Technical Support for analysis of your application and its environment.

**Note:**

If you have difficulty reaching Avaya Technical Support through the above URL or email address, please go to <http://www.avaya.com> for further information.

When you request technical support, provide the following information:

- Configuration settings, including Communication Manager configuration and browser settings.
- Usage scenario, including all steps required to reproduce the issue.
- Screenshots, if the issue occurs in the Administration Application, one-X Portal, or one-X Portal Extensions.
- Copies of all logs related to the issue.
- All other information that you gathered when you attempted to resolve the issue.



**Tip:**

Avaya Global Services Escalation Management provides the means to escalate urgent service issues. For more information, see the [Escalation Contacts](#) listings on the Avaya Web site.

For information about patches and product updates, see the Avaya Technical Support Web site <http://www.avaya.com/support>.



# Appendix A: Acronyms

|             |   |
|-------------|---|
| <b>AAR</b>  | Automatic Alternate Routing   |
| <b>ACD</b>  | Automatic Call Distribution   |
| <b>AES</b>  | Application Enablement Services   |
| <b>ARS</b>  | Automatic Route Selection   |
| <b>ASAI</b> | Adjunct Switch Applications Interface   |
| <b>AVP</b>  | Avaya Voice Portal  |
| <b>AWOH</b> | Administered WithOut Hardware   |
| <b>BA</b>   | Bridge Appearance   |
| <b>BRI</b>  | Basic Rate Interface  |
| <b>BTD</b>  | Busy Tone Disconnect  |
| <b>CDR</b>  | Call Detail Record  |
| <b>CLI</b>  | Command Line Interface  |
| <b>CLAN</b> | TN799 Control LAN circuit pack that controls TCP/IP signalling and firmware downloads |
| <b>CMA</b>  | Call Management System  |
| <b>CMS</b>  | Call Management System  |
| <b>CNC</b>  | Control Network C   |
| <b>CPU</b>  | Central Processing Unit   |
| <b>CTI</b>  | Computer Telephony Integration  |
| <b>DCP</b>  | Digital Communications Protocol   |
| <b>DCS</b>  | Distributed Communication System  |
| <b>DECT</b> | Digitally Enhanced Cordless Telecommunications  |
| <b>DPT</b>  | Dial Plan Transparency  |
| <b>DTMF</b> | Dual Tone Multi-Frequency   |
| <b>EAS</b>  | Expert Agent Selection  |
| <b>ESS</b>  | Enterprise Survivable Server  |
| <b>FAC</b>  | Feature Access Code   |
| <b>FNE</b>  | Feature Name Extension  |
| <b>HDX</b>  | A Polycom high definition video room system   |
| <b>HEMU</b> | Home Enterprise Mobility User   |
| <b>IGAR</b> | Inter-Gateway Alternate Routing   |

## Appendix A: Acronyms

|              |  |
|--------------|--|
| <b>IP</b>    | Internet Protocol  |
| <b>IPSI</b>  | Internet Protocol Server Interface   |
| <b>ISDN</b>  | Integrated Services Digital Network  |
| <b>ISG</b>   | Integrated Services Gateway  |
| <b>J24</b>   | Avaya Digital Terminal for Japan   |
| <b>LAN</b>   | Local Area Network   |
| <b>LAI</b>   | Look Ahead Interflow   |
| <b>LAR</b>   | Look Ahead Routing   |
| <b>LED</b>   | Light Emitting Diode   |
| <b>LSP</b>   | Local Survivable Processor   |
| <b>OPTIM</b> | Off-Premise Telephony Integration with MultiVantage                                |
| <b>MG</b>    | Media Gateway  |
| <b>MGC</b>   | Media Gateway Controller   |
| <b>MIB</b>   | Management Information Base  |
| <b>MOH</b>   | Music on Hold  |
| <b>MPC</b>   | Maintenance Processor Complex  |
| <b>NCR</b>   | Network Call Redirection   |
| <b>PAM</b>   | Pluggable Authentication Modules   |
| <b>PE</b>    | Processor Ethernet   |
| <b>PSA</b>   | Personal Station Access  |
| <b>PSTN</b>  | Public Switched Telephone Network  |
| <b>PCD</b>   | Packet Control Driver  |
| <b>QSIG</b>  | International Standard for inter-PBX feature transparency at the Q reference point |
| <b>RDTT</b>  | Reliable Data Transport Tool   |
| <b>RMB</b>   | Remote Maintenance Board   |
| <b>RMX</b>   | A Polycom media conferencing platform, used by CM as a video and audio bridge      |
| <b>RTP</b>   | Real-Time Protocol   |
| <b>SAC</b>   | Send All Calls   |
| <b>SAT</b>   | System Access Terminal   |
| <b>SBA</b>   | Simulated Bridge Appearance  |
| <b>SBC</b>   | Separation of Bearer and Signaling   |
| <b>SBS</b>   | Separation of Bearer and Signaling   |
| <b>SES</b>   | SIP Enablement Services  |
| <b>SIP</b>   | Session Initiation Protocol  |

|             |   |
|-------------|---|
| <b>SDP</b>  | Session Description Protocol                    |
| <b>SMI</b>  | System Management Interface                     |
| <b>SVNS</b> | Simple Voice Network Statistics                 |
| <b>TAC</b>  | Trunk Access Code                               |
| <b>TCP</b>  | Transmission Control Protocol                   |
| <b>TDM</b>  | Time Division Multiplex                         |
| <b>TSP</b>  | Toshiba SIP Phone                               |
| <b>TSRA</b> | Time Slot Record Audit                          |
| <b>TTI</b>  | Terminal Translation Initialization             |
| <b>URI</b>  | Uniform Resource Identifier                     |
| <b>USNI</b> | United States Network Interface                 |
| <b>USB</b>  | Universal Serial Bus                            |
| <b>VALU</b> | Value-Added                                     |
| <b>VDN</b>  | Vector Directory Number                         |
| <b>VOA</b>  | VDN of origin Announcement                      |
| <b>VEMU</b> | Visitor Enterprise Mobility User                |
| <b>VLAN</b> | Virtual Local Area Network                      |
| <b>VSX</b>  | A Polycom standard definition video room system |