

Ethernet Routing Switch 3500 Series

Software Release 5.3.2.207

1. Release Summary

Release Date: 22-August-2016

Purpose: Software maintenance release to extend the FA Proxy to all 3500 models and to address internally found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch 3500 (All models).

4. Notes for Upgrade

Please see “Ethernet Routing Switch 3500 Series, Configuration – System, Software Release 5.3” (available at <http://www.avaya.com/support>. Click Products, select Ethernet Routing Switch 3500 Series from the A-Z list, then select Documentation > View All Documents) for details on how to upgrade your Switch.

File Names for This Release

File Name	Module or File Type	File Size (bytes)
3500_53007_diag.bin	Diagnostic image	2091101
3500_532206.img	Agent code image	9,514,244
3500_532207s.img	Agent code image (SSH)	9,777,140

5. Version of Previous Release

Software Version 5.3.2

6. Compatibility

This software release is managed with Enterprise Device Manager (EDM) which is integrated into the agent software.

7. Changes in This Release

7.1. New Features in This Release

Full FA Proxy support for all SKUs.

7.2 Old Features Removed From This Release

None.

7.3 Problems Resolved in This Release

None.

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

None.

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: <http://www.avaya.com/support> .

11. Troubleshooting

As good practices of help for troubleshooting various issues, AVAYA recommends:

- configuring the device to use the Simple Network Time Protocol to synchronize the device clock;
- setting a remote logging server to capture all level logs, including informational ones. (#logging remote level informational).

Copyright © 2015 Avaya Inc - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Avaya.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <http://www.avaya.com/support>.