Additional Details - Engagement Solutions Updated July 2018

As of August 31, 2018, Avaya will stop distributing Communication Manager 6.3.11 through 6.3.18. The table below has been updated to reflect this change. See also PSN020262u: <u>https://downloads.avaya.com/css/P8/documents/101026404</u>

Avaya has stopped using a specific piece of embedded software contained within certain product versions. On May 31, 2018, Avaya stopped distributing patches or specific versions of certain legacy products. Please see the affected product versions and recommended actions below. If affected products are in use in your production environment --

Upgrade to a release or product line that is not affected, as recommended below.

Or plan to upgrade after any failure that requires a re-install. Expect extended outage periods.

Release	Release Lifecycle Phase	Action
6.3.111 through 6.3.118	End of Manufacturer Support	No action required
6.3 through 6.3.18	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
6.2.0	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
6.0.1	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
6.0.0	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.2.1	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.2.0	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.1.2	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.1.1	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.1.0	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
5.0.0	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
R4	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
R3	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater
R2 and lower	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater

Avaya Aura Messaging

Release	Release Lifecycle Phase	Action
Older than 6.3.3	End of Manufacturer Support	Upgrade to AAM 7.0 (current) or AAM 6.3.3 SP7

Communication Manager Messaging including Federal Market edition

Release	Release Lifecycle Phase	Action
Older than 6.3.100	End of Manufacturer Support	Upgrade to 6.3.111 or greater or 7.x or greater

Meeting Exchange

Release	Release Lifecycle Phase	Action
5.2 and older	End of Manufacturer Support	Upgrade to Meeting Exchange 6.2.x

Media Gateway

Release	Release Lifecycle Phase	Action
G700	End of Manufacturer Support	Move to a current product line
G250	End of Manufacturer Support	Move to a current product line
G350	End of Manufacturer Support	Move to a current product line
G430	Currently Shipping	Use the latest FW version available on Avaya Support that is compatible with your CM Release (6.x or 7.x)
G450	Currently Shipping	Use the latest FW version available on Avaya Support that is compatible with your CM Release (6.x or 7.x)
TGM 550	End of Manufacturer Support	Move to a current product line

Boards

Release		Action
		Upgrade to 5/4/2014 release of: TN799DP HV0-10, FW44 OR
TN799	Currently Shipping	TN799DP HV13+, FW44
TN2501	Currently Shipping	Upgrade to 5/4/2014 release of: TN2501AP HW V0-3, FW23 OR
		TN2501AP HW V13+, FW23

Media Processing Server (MPS)

Release		Action
3.x Older than Release 3.5 Patch Bundle 6	End of Manufacturer Support	Upgrade to 4.1 Patch Bundle 4
4.x Older than Release 4.1 Patch Bundle 1	End of Manufacturor Support	Upgrade to 4.1 Patch Bundle 4
Bundle 1		Opgrade to 4.1 Patch Bullule 4

Business Communication Manager

Release		Action
BCM 1000	End of Manufacturer Support	Move to a current product line
BCM 200/400	End of Manufacturer Support	Move to a current product line
BCM 50/450 (aka SRG50)	End of Manufacturer Support	Move to a current product line

Avaya product lifecycle summary:

https://support.avaya.com/css/P8/documents/100172510

Avaya product lifecycle policy document:

https://downloads.avaya.com/css/P8/documents/100081098

Additional Details - Extreme Networking

Updated April 2018 (no changes in July 2018)

For the latest product releases, please contact Extreme Networks:

https://www.extremenetworks.com/avaya-support-transition/

ERS 2500

Release	Release Lifecycle Phase	Action
4.4.3	Extended Services Support	Refresh network using ERS 3500
All prior versions	End of Services Support/EOL	Refresh network using ERS 3500

ERS 3500

Release	Release Lifecycle Phase	Action
5.3.x and greater	GA	No action required
5.2.x	Extended Services Support	Upgrade to latest 5.3.x version
All prior versions	End of Services Support/EOL	Upgrade to latest 5.3.x version

ERS 4500

Release	Release Lifecycle Phase	Action
5.7.x	Extended Services Support	Refresh network using ERS 4900
All prior versions	End of Services Support/EOL	Refresh network using ERS 4900

ERS 4800

Release	Release Lifecycle Phase	Action
5.9.x and greater	GA	No action required
5.8.x	Extended Services Support	Upgrade to latest 5.9.x version
5.7.x	Extended Services Support	Upgrade to latest 5.9.x version
All prior versions	End of Services Support/EOL	Upgrade to latest 5.9.x version

ERS 5500

Release	Release Lifecycle Phase	Action
6.3.x	Extended Services Support	Refresh network using ERS 5900
All prior versions	End of Services Support/EOL	Refresh network using ERS 5900

ERS 5600

Release	Release Lifecycle Phase	Action
6.6.x	Extended Services Support	Refresh network using ERS 5900
6.3.x	Extended Services Support	Refresh network using ERS 5900
All prior versions	End of Services Support/EOL	Refresh network using ERS 5900

VSP 7024

Release	Release Lifecycle Phase	Action
10.4.x	GA	No action required
10.3.x	Extended Services Support	Upgrade to latest 10.4.x version
All prior versions	End of Services Support/EOL	Upgrade to latest 10.4.x version

WLAN 8100 Controller

Release	Release Lifecycle Phase	Action
3.0.x	Extended Services Support	Refresh network using WLAN 9100
All prior versions	End of Services Support/EOL	Refresh network using WLAN 9100