

Sun Alert Notifications from Sun Summary Report dated July 9, 2005 (SUN-101758, SUN-101771, SUN-101784, SUN-101794, SUN-101799)

Advisory Original Release Date: July 26, 2005

Last Revised: August 2, 2005

Number: ASA-2005-162

Risk Level: Low

Advisory Version: 2.0

Advisory Status: Interim

Overview:

New Sun Alert Notifications from Sun Microsystems have been issued and are described as follows. Issues which have been resolved by Sun Microsystems have been indicated as such. Notifications without a resolution may have restrictions to additional information on the sunsolve.sun.com web site.

101758 (RESOLVED by Sun)

Loss of Access to 3510 or 3511 FC Storage After Power Cycle of Host Using 1 Gb PCI Dual FC Host Adapter(+) HBA

Date Released: 29-Jun-2005

<http://sunsolve.sun.com/search/document.do?assetkey=1-26-101758-1>

101771

Certain SCSI Patches May Cause Disk Drives DK32EJ72N, DK32EJ36N, DK32EJ14N, DK32EJ36F, DK32EJ72F, and DK32EJ14F to Become Inaccessible

Date Released: 01-Jul-2005

<http://sunsolve.sun.com/search/document.do?assetkey=1-26-101771-1>

101784 (RESOLVED by Sun)

Non-Interactive ssh(1) Sessions May Hang After Remote Command Has Exited

Date Released: 28-Jun-2005

<http://sunsolve.sun.com/search/document.do?assetkey=1-26-101784-1>

101794

Security vulnerability in the Solaris runtime linker (ld.so.1(1))

Date Released: 28-Jun-2005

<http://sunsolve.sun.com/search/document.do?assetkey=1-26-101794-1>

101799 (RESOLVED by Sun)

Security Vulnerability in JRE Plug-in affects the Sun Java Desktop System for Linux

Date Released: 01-Jul-2005

<http://sunsolve.sun.com/search/document.do?assetkey=1-26-101799-1>

Avaya System Products using Sun Microsystems: Avaya system products include an Operating System with the product when it is delivered. The Avaya **Call Management System** (CMS) and the Avaya **Interactive** Response (IR) are

taken on these products are described below.

Recommended Actions: Follow the recommended actions for each notification described below. This advisory will be updated as additional information becomes available.

<u>Sun Advisory</u>	<u>Affected S/W Version</u>	<u>Risk</u>	<u>Comments or Recommended Actions</u>
101758	NONE	None	No action required. CMS and IR are not affected; StorEdge is not used.
101771	CMS R13 on v880/v890	Low	Patch from Sun is pending. Install patch when available from Sun.
101784	CMS R12, R13	Low	CMS R12,R13 – Install patch 114356-04 IR & CMS R9, 10, 11 - No action required. CMS R9, 10, 11 and IR do not use x86 versions of Solaris.
101794	CMS & IR	Low	Avaya is currently investigating the potential risks of this issue.
101799	NONE	None	No action required. CMS and IR are not affected; Java Desktop System (JDS) is not used.

Additional Information: Additional information may also be available via the Avaya support website (<http://support.avaya.com>) and through your Avaya account representative. Please contact your Avaya product support representative, or dial 1-800-242-2121, with any questions.

Disclaimer: ALL INFORMATION IS BELIEVED TO BE CORRECT AT THE TIME OF PUBLICATION AND IS PROVIDED "AS IS". AVAYA INC., ON BEHALF ITSELF AND ITS SUBSIDIARIES AND AFFILIATES (HEREINAFTER COLLECTIVELY REFERRED TO AS "AVAYA"), DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND FURTHERMORE, AVAYA MAKES NO REPRESENTATIONS OR WARRANTIES THAT THE STEPS RECOMMENDED WILL ELIMINATE SECURITY OR VIRUS THREATS TO CUSTOMERS' SYSTEMS. IN NO EVENT SHALL AVAYA BE LIABLE FOR ANY DAMAGES WHATSOEVER ARISING OUT OF OR IN CONNECTION WITH THE INFORMATION OR RECOMMENDED ACTIONS PROVIDED HEREIN, INCLUDING DIRECT, INDIRECT, CONSEQUENTIAL DAMAGES, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF AVAYA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

THE INFORMATION PROVIDED HERE DOES NOT AFFECT THE SUPPORT AGREEMENTS IN PLACE FOR AVAYA PRODUCTS. SUPPORT FOR AVAYA PRODUCTS CONTINUES TO BE EXECUTED AS PER EXISTING AGREEMENTS WITH AVAYA.

Revision History:

V 1.0 – July 26, 2005 – Initial statement issued.

V 2.0 – August 2, 2005 – Clarified statements for 101784

Send information regarding any discovered security problems with Avaya products to either the contact noted in the product's documentation or securityalerts@avaya.com.

© 2005 Avaya Inc. All Rights Reserved. All trademarks identified by the ® or ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners.