



End of Sale Notice

Notification Date: 02-June-2014
Revision: 09-June-2014 (see new support schedule)
Effective Date: 06-Oct-2014 for material specified
Subject: End of Sale of G450 MP80 Configuration
Theatre/Region: All

Summary

Effective Oct 06, 2014, Avaya will no longer sell (make commercially available) the G450 MP80 configuration highlighted in table 1 below.

Avaya will make every effort to have a supply of these products available for orders, but cannot guarantee product availability through their end of sale dates. Avaya reserves the right to manage and/or limit order quantities, substitute like materials, or to cancel orders if supply is exhausted prior to the End of Sale dates in this notice.

Manufacturer Discontinued Codes and Migration Strategy

Manufacturer Discontinued Codes

The following Avaya material codes will be manufacturer discontinued as of Oct 6, 2014.

| Material Code | Description |
|---------------|----------------------------------|
| 700407802 | G450 MP80 W/POWER SUPPLY |
| 700459456 | G450 MP80 W/POWER SUPPLY NON-GSA |

Table 1: List of End of Sale codes

Note: Starting on July 1, 2014, the material codes above will be changed to "Manufactured Retired upon Stock Depletion" (MRSD) status. As its name implies, the material codes will continue to be available for sale as long as there is stock. When the stock is depleted, existing quote(s) will need to be revised using the new replacement codes in Table 2 under the **Migration Strategy** section.

Migration Strategy

Avaya has offered the new G450 MP160 configuration below as the replacement product. Note that this new configuration comes with an embedded MP160 Daughter Board that offer twice as much DSP channel capacity as the discontinued G450 MP80 configuration.

| Material Code | Description |
|---------------|----------------------------------|
| 700506955 | G450 MP160 MEDIA GATEWAY |
| 700506956 | G450 MP160 MEDIA GATEWAY NON GSA |



Table 2: List of replacement codes

If you have questions, or would like more information about additional Avaya products, please contact your Avaya representative or Avaya authorized Partner.

Schedule

| | |
|---|--------------|
| Material code changed to MRSD status | 01-July-2014 |
| Automatic EoS Notification via GPPC | 06-Aug-2014 |
| End of Sale Date (when material codes changed to D status) | 06-Oct-2014 |
| End of Manufacturer Support for SOFTWARE * | 06-Oct-2020 |
| End of Manufacturer Support for HARDWARE * | 06-Oct-2020 |
| Last day to purchase system expansions | N/A |
| Targeted End of Services Support ** | 06-Oct-2023 |

* Per Avaya Product Lifecycle Policy

**Avaya Services may revise the Target End of Services Support date based on the availability of quality repair parts and/or technical support expertise. Customers should always consult any available product Services Support Notices for final information on product supportability.



Service and Warranty

Avaya will continue to honor previously executed enhanced warranty, post-warranty and service contracts in accordance with the terms of those agreements. Avaya is not responsible for any support or maintenance commitments made by Business Partners or other service providers. Additional information concerning Avaya Services can be found on the [Services Offer Information](#) Web site.

Renewals of existing Avaya service contracts covering this product will be for at least 3 years

Additional Information

Avaya website:

<http://www.avaya.com>

Avaya End-of-Sale Notices:

<http://support.avaya.com>

Avaya Product Lifecycle Policy:

<https://support.avaya.com/css/P8/documents/100081098>

or

<http://support.avaya.com> >> More Resources >> More >> Avaya Product Lifecycle Policy